

REGION II
TENNESSEE VALLEY AUTHORITY
ATLANTA
CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

83 JUL 15 P 1:52

July 8, 1983

BLRD-50-438/82-40

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNIT 1 - OVERPRESSURIZATION OF MAKEUP AND
PURIFICATION PIPING AND VALVES - BLRD-50-438/82-40 - SUPPLEMENTAL FINAL
REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
D. Quick on May 28, 1982 in accordance with 10 CFR 50.55(e) as NCR 1808.
This was followed by our interim reports dated June 28 and August 10,
1982, our final report dated October 12, 1982, and our revised final report
dated February 3, 1983.

As discussed with NRC-OIE Inspector Linda Watson on June 30, 1983, the date
of June 30, 1983 for completion of corrective actions indicated in our
revised final report on this matter will not be met. Valve VIBB-439-A was
found to have a leakage rate greater than that allowed by the design
specifications. Accordingly, the subject valve will be reworked and
retested. All other valves are acceptable. The corrective action on this
matter will be completed by October 14, 1983.

If you have any questions concerning this matter, please get in touch with
R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills
L. M. Mills, Manager
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

OFFICIAL COPY

1983-TVA 50TH ANNIVERSARY

An Equal Opportunity Employer

8307220321 830708
PDR ADDCK 05000438
S PDR

TE-27 1/0