

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

July 15, 1983

TELEPHONE
(704) 373-4531

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street NW, Suite 2900
Atlanta, Georgia 30303

Subject: McGuire Nuclear Station Unit 1
Docket No. 50-369
LER/RO-369/83-46

83 JUL 22 A10:07
USNRC REGION I
ATLANTA, GEORGIA

Dear Mr. O'Reilly:

Reportable Occurrence Report RO-369/83-46 was to have been submitted by July 15, 1983. This 30 day Reportable Occurrence (per T.S. 6.9.1.11) concerns T.S. 3.7.6, "Two independent control area ventilation systems shall be operable", which was violated on June 17, 1983. At this time investigation of the incident and preparation of the report are not yet complete. The report will be submitted by July 29, 1983.

Very truly yours,

H.B. Tucker

Hal B. Tucker

PBN:jfw

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

Mr. W. T. Orders
NRC Resident Inspector
McGuire Nuclear Station

8307260462 830715
PDR ADDCK 05000369
S PDR

OFFICIAL COPY
IE 22
1/0