

PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET

P.O. BOX 8699

PHILADELPHIA, PA. 19101

EDWARD G. BAUER, JR.
VICE PRESIDENT
AND GENERAL COUNSEL

(215) 841-4000

EUGENE J. BRADLEY
ASSOCIATE GENERAL COUNSEL

DONALD BLANKEN
RUDOLPH A. CHILLEMI
E. C. KIRK HALL
T. H. MAHLER CORNELL
PAUL AUERBACH

ASSISTANT GENERAL COUNSEL

EDWARD J. CULLEN, JR.

THOMAS H. MILLER, JR.

IRENE A. MCKENNA
ASSISTANT COUNSEL

July 25, 1983

Mr. A. Schwencer, Chief
Licensing Branch No. 2
Division of Licensing
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Subject: Limerick Generating Station, Units 1 and 2
Procedures and Test Review Branch

Reference: PECO and NRC Conference Call dated 7/15/83

File: GOVT 1-1 (NRC)

Dear Mr. Schwencer:

As a result of the discussions in the reference conference call with the Operating and Maintenance Procedures Branch reviewer, the attached revised draft FSAR page changes to TAP I.C.8 will be incorporated into the FSAR exactly as it appears on the attachments in the revision scheduled for August, 1983.

Sincerely,


Eugene J. Bradley

RJS/gra/42

Copy to: See Attached Service List

8307280330 830725
PDR ADOCK 05000352
A PDR

Boo!
1/1

cc: Judge Lawrence Brenner	(w/o enclosure)
Judge Richard F. Cole	(w/o enclosure)
Judge Peter A. Morris	(w/o enclosure)
Troy B. Conner, Jr., Esq.	(w/o enclosure)
Ann P. Hodgdon	(w/o enclosure)
Mr. Frank R. Romano	(w/o enclosure)
Mr. Robert L. Anthony	(w/o enclosure)
Mr. Marvin T. Lewis	(w/o enclosure)
Judith A. Dorsey, Esq.	(w/o enclosure)
Charles W. Elliott, Esq.	(w/o enclosure)
Jacqueline I. Ruttenberg	(w/o enclosure)
Thomas Y. Au, Esq.	(w/o enclosure)
Mr. Thomas Gerusky	(w/o enclosure)
Director, Pennsylvania Emergency Management Agency	(w/o enclosure)
Mr. Steven P. Hershey	(w/o enclosure)
Donald S. Bronstein, Esq.	(w/o enclosure)
Mr. Joseph H. White, III	(w/o enclosure)
David Wersan, Esq.	(w/o enclosure)
Robert J. Sugarman, Esq.	(w/o enclosure)
Martha W. Bush, Esq.	(w/o enclosure)
Spence W. Perry, Esq.	(w/o enclosure)
Atomic Safety and Licensing Appeal Board	(w/o enclosure)
Atomic Safety and Licensing Board Panel	(w/o enclosure)
Docket and Service Section	(w/o enclosure)

• I.C.6 VERIFY CORRECT PERFORMANCE OF OPERATING ACTIVITIESPosition

It is required (from NUREG-0660) that licensees' procedures be reviewed and revised, as necessary, to assure that an effective system of verifying the correct performance of operating activities is provided as a means of reducing human errors and improving the quality of normal operations. This will reduce the frequency of occurrence of situations that could result in or contribute to accidents. Such a verification system may include automatic system status monitoring, human verification of operations, and maintenance activities independent of the people performing the activity (see NUREG-0585, Recommendation 5), or both.

Response

Plant procedures will describe a system for the control of removal and restoration and alignment of safety-related plant systems or equipment. This system will use a combination of control room indicators, operability testing, or independent verification (subject to radiation exposure limitations), to ensure that equipment is in its correct alignment.

• I.C.7 NSSS VENDOR REVIEW OF PROCEDURESPosition

Obtain nuclear system supply system vendor review of power-ascension and emergency operating procedures to further verify their adequacy.

Response

This requirement will be implemented.

• I.C.8 PILOT MONITORING OF SELECTED EMERGENCY PROCEDURES FOR NEAR-TERM OPERATING LICENSE APPLICANTSPosition

Correct emergency procedures as necessary based on the NRC audit of selected plant emergency operating procedures (e.g., small-break loss-of-coolant accident, loss of feedwater, restart of engineered safety features following a loss of ac power and steam-line break).

Response

~~This requirement will be implemented.~~ → *insert next page*

DRAFT

Information on ^{emergency ~~pro~~ procedures} (NUREG - 0737, Item I. C. 1) was provided to the NRC in a response (Letter from V. S. Boyer to D. G. Cisneros dated April 15, 1983) to Generic Letter 82-33, Supplement 1 to NUREG - 0737. Emergency operating procedures have been developed from the BWR Owners Group Emergency Procedure Guideline, Revision 2.

Insert for page 1.13 - 16