

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

July 22, 1983

TELEPHONE
(704) 373-4531

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Attention: Ms. E. G. Adensam, Chief
Licensing Branch No. 4

Re: McGuire Nuclear Station
Docket Nos. 50-369, 50-370


Dear Mr. Denton:

McGuire Nuclear Station, Unit 2, Facility Operating License NPF-17 requires that Duke Power Company provide "...the upgr a ed post-trip review procedures for NRC staff review" (Paragraph 2.C.(12)d.). By letter dated May 20, 1983 Duke notified the NRC staff that the "Reactor Trip", "Unit Fast Recovery" and "Controlling Procedure for Unit Startup" procedures were changed to require that the evaluation conducted by the Performance Group be completed prior to restart following a reactor trip. Accordingly, a copy of each of these procedures is hereby submitted.

It should be noted that future changes in this area are likely as a result of requirements issued in Generic Letter 83-28 "Required Actions Based on Generic Implications of Salem ATWS Events". Any additional changes relative to post-trip review will be described in the report required by Sections 1.1 and 1.2 of the enclosure to Generic Letter 83-28.

Please advise if there are any questions regarding this matter.

Very truly yours,


Hal B. Tucker

GAC:php

cc: Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street NW, Suite 2900
Atlanta, Georgia 30303

Mr. W. T. Orders
NRC Resident Inspector
McGuire Nuclear Station

8307280409 830722
PDR ADOCK 05000369
P PDR

Boo!
//