

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 F L S L S 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
 LICENSE CODE LICENSE NUMBER LICENSE TYPE CAT

CON'T
 01 REPORT SOURCE L 6 0 5 0 0 0 3 8 9 7 0 6 2 3 8 3 3 0 7 2 5 8 3 9
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
 DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
 02 DURING POWER ASCENSION TESTING WHILE AT HOT ZERO POWER, CHANNEL "A" WIDE
 03 RANGE NI FAILED. ACTION WAS TAKEN IN ACCORDANCE WITH T.S. 3.3.1 AND THE
 04 CHANNEL WAS PLACED IN BYPASS. THIS WAS THE FIRST EVENT OF THIS TYPE.
 05 THERE WAS NO ADVERSE EFFECT ON THE HEALTH OR SAFETY OF THE PUBLIC.
 06
 07
 08
 09

SYSTEM CODE I A 11 CAUSE CODE E 12 CAUSE SUBCODE G 13 COMPONENT CODE I N S T R U 14
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
 LEAD REPORT NUMBER 17 8 3 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
 EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO. COMPONENT MANUFACTURER
 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
 ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP SUPPLIER
 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
 10 THE CHANNEL "A" WIDE RANGE NI FAILED DUE TO THE FAILURE OF A LOG COUNT
 11 RATE CIRCUIT BOARD LCR-1 MANUFACTURED BY ELECTRO MECHANIC. NO CAUSE FOR
 12 THE LCR-1 FAILURE WAS DETERMINED. THE BOARD WAS REPLACED AND THE CHANNEL
 13 RESTORED TO OPERABLE STATUS.
 14
 15 FACILITY STATUS B 28 0 0 0 0 29 30 NA 31 A 32 Operator Observation
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
 ACTIVITY CO INT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
 15 Z 33 Z 34 NA 35 NA 36
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
 17 0 0 0 17 Z 38 NA 39
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
 PERSONNEL INJURIES NUMBER DESCRIPTION
 18 0 0 0 40 NA 41
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
 19 Z 42 NA 43
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
 PUBLICITY ISSUED DESCRIPTION
 20 N 44 NA 45
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
 NAME OF PREPARER G. E. Walling PHONE 305-465-3550 ext. 3580

USNRC REGION II
ATLANTA, GEORGIA



83 JUL 28 09:28

July 25, 1983
PNS-LI-83-515-1

Mr. James P. O'Reilly
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta Street N.W., Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 389-83-32

ST. LUCIE UNIT 2


DATE OF OCCURRENCE: JUNE 23, 1983

TECHNICAL SPECIFICATION 3.3.1

CHANNEL "A" WIDE RANGE NUCLEAR INSTRUMENTATION

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,


J. W. Williams, Jr.
Vice President
Nuclear Energy

JWW/PLP/js

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Harold F. Reis, Esquire
File 933.1 SL

OFFICIAL COPY

IE 22