




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P O BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 386-2345

July 25, 1983

W3I83-0244
Q-3-A35.07.70

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 70
"GE 480-V Trip Coils Do Not Drop Out After Tripping"
Fourth Interim Report

REFERENCE: LP&L letter W3I83-0227 dated June 22, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC no later than July 22, 1983.

At the present time, LP&L is in the process of finalizing the review of supporting documentation for SCD 70. This review is expected to be completed by August 12, 1983.

A Final Report will therefore be submitted to the USNRC by September 12, 1983.

Very truly yours,

F. J. Drummond
Project Support Manager - Nuclear

FJD/RWP/MAL:keh

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

3) Mr. E. L. Blake

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

4) Mr. W. M. Stevenson

8308030408 830725
PDR ADOCK 05000382
S PDR

IE-27.10