



**LOUISIANA
POWER & LIGHT**


142 DELARONDE STREET • P.O. BOX 8008
NEW ORLEANS, LOUISIANA 70174-8008 • (504) 366-2345

August 2, 1983

W3I83-0251
Q-3-A35.07.63

Mr. John T. Collins, Regional Administrator, Region IV
U.S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 63
"Procurement of Spare/Replacement Parts"
Third Interim Report



REFERENCE: LP&L Letter W3I83-0121 dated April 15, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report by July 29, 1983.

At the present time, approximately 100 purchase orders for safety-related and/or quality-related spare and replacement parts have been reviewed out of the total 310 purchase orders identified in the reference above. All identified deficiencies in these packages have been corrected to allow their use in the applications for which they were ordered. The remaining purchase orders are in various stages of review. It is estimated that the documentation review and corrective action for the identified purchase orders will be completed by October 28, 1983.

A Final Report will therefore be submitted by November 30, 1983.

Very truly yours,

F. J. Drummond
Project Support Manager-Nuclear

FJD/WAC/MAL/ch

cc: 1) Director
Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

3) Mr. E. L. Blake

2) Director
Office of Management
Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

4) Mr. W. M. Stevenson

8308120148 830802
PDR ADDCK 05000382
S PDR

IE-27

110