




**LOUISIANA
POWER & LIGHT**

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

July 29, 1983

W3183-0259
Q-3-A35.07.79

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 79
"Unqualified Components in Hydrogen Analyzers"
Third Interim Report

REFERENCE: LP&L letter W3183-0211 dated June 15, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC no later than July 29, 1983.

At the present time, documentation is being prepared to initiate the installation of the qualified replacement pump motors. This installation is expected to be complete by the end of August.

A Final Report will therefore be submitted to the USNRC by September 16, 1983.

Very truly yours,

F. J. Drummond
Project Support Manager - Nuclear

FJD/WAC/MAL:keh

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

3) Mr. E. L. Blake

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

4) Mr. W. M. Stevenson

8308160407 830727
PDR ADOCK 05000382
S PDR

IE-27 1/0