



Docket No. 50-346

License No. NPF-3

Serial No. 1-362

June 8, 1983

James G. Keppler
Regional Administrator
U. S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

RICHARD P. CROUSE
Vice President
Nuclear
(419) 258-5221

orig + 1

PRINCIPAL STAFF			
✓ RA	<i>Karen</i>	ENF	
D/RA		SCS	
A/BA		PAO	
✓ OPRP		SLO	
DRMA		RC	
DRMSF			
DE			
ML			
OL		FILE	<i>Ken</i>

Dear Mr. Keppler:

In response to 10CFR50.54(a)(2), a current description of the Toledo Edison Quality Assurance Program for the Davis-Besse Nuclear Power Station Unit No. 1 is enclosed. This revision to Chapter 17.2 of the SAR is a complete revision to the Chapter 17.2 originally contained within the FSAR. The more significant changes relate to the following:

1. Title and Organizational changes made since the issuance of the FSAR.
2. Upgrading of the NRC Regulatory Guide and ANSI Standard commitments from those revisions contained in the Gray, Green, and Orange Books to more current revisions. The committed edition of those NRC Regulatory Guides referenced within the Davis-Besse Unit #1 Technical Specifications has not been changed.
3. Position statements which describe Toledo Edison's compliance with the referenced NRC Regulatory Guide and ANSI Standard requirements have been developed and included into Chapter 17.2.
4. Chapter 17.2 has been rewritten to provide more specific details of the Quality Assurance Program than those contained in the original FSAR Chapter 17.2.

Very truly yours,

R P Crouse / tcn

RPC/CTD

jc c/41

Enclosure

8308160516 830608
PDR ADOCK 05000346
P PDR

JUN 13 1983

cc: DB-1 Resident Inspector

1E01
11