

CONTROL BLOCK:

--	--	--	--	--	--	--

 ① (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	9
---	---

(17) LER/RO REPORT NUMBER 83 21 32 33

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER						
X	18	Z	19	Z	20	Z	21	0	0	0	0	N	23	Y	24	A	25	H	1	9	8	26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

7	8
1	5

FACILITY STATUS		% POWER		OTHER STATUS (30)		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION (32)	
G (18)		0	0	0	(29) N/A	A (31)		Operator observation	

1	2
---	---

PERSONNEL EXPOSURES			DESCRIPTION	
NUMBER	TYPE			
000	Z	N/A		

7 3
1 9

LOSS OF OR DAMAGE TO FACILITY	(43)
TYPE	DESCRIPTION
Z (42)	N/A

7 3

NAME OF PREPARER Jesus Arias, Jr. PHONE 305/245-2910 X-200

USNRC REGION II
ATLANTA, GEORGIA

83 SEP 7 49:02



September 2, 1983
PNS-LI-83-588-1

Mr. James P. O'Reilly
Regional Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta Street N.W., Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 251-83-009

TURKEY POINT UNIT 4

DATE OF OCCURRENCE: AUGUST 3, 1983

TECHNICAL SPECIFICATION 3.9.1.i

STEAM GENERATOR BLOWDOWN ISOLATION

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,

A handwritten signature in dark ink, appearing to read "J. Williams, Jr.", written over a horizontal line.

J. W. Williams, Jr.
Vice President
Nuclear Energy

JWW/PKG/js

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Harold F. Reis, Esquire
File 933.1 TP

OFFICIAL COPY

IE 22

PEOPLE . . . SERVING PEOPLE