



J. Phillip Bayne  
Executive Vice President  
Nuclear Generation

September 21, 1983  
JPN-83-83

Director of Nuclear Reactor Regulation  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Attention: Mr. Domenic B. Vassallo, Chief  
Operating Reactors Branch No. 2  
Division of Licensing

Subject: James A. FitzPatrick Nuclear Power Plant  
Docket No. 50-333  
Additional Information Concerning a Potential  
Pipe Support Design Non-Conformance

Reference: NYPA letter J. P. Bayne to D. B. Vassallo,  
dated September 1, 1983 (JPN-83-79), concern-  
ing the same subject.

Dear Sir:

In the reference letter, the Power Authority provided the status of our review of a potential pipe support design non-conformance. The purpose of this letter is to provide additional information on the status of our review, and to clarify information contained in the reference letter.

As stated in the reference letter, our consultant provided us with a list of 20 supports which he identified as potentially non-conforming. The consultant claimed that the list of 20 included some supports which show evidence of physical damage. Of these 20 supports, only 18 still exist in their original configuration and location. These 18 supports were visually inspected and 17 were found to be undamaged and acceptable in the as-found condition. The condition of the remaining support, on the main steam line, was described in the reference letter.

The 2 supports not visually inspected have been redesigned or relocated as a result of the Mark I program. One of these original supports was removed during the 1981-82 refueling outage.

8309230111 830921  
PDR ADOCK 05000333  
S PDR


A001  
1/0

The other support was redone during the 1983 refueling outage before it could be inspected.

The independent third party review by United Engineers and Constructors (UE&C) is continuing. UE&C has informed us that their review to date has not resulted in any significant findings. Due to the extent of the UE&C review, it will not be completed within 2 to 4 weeks as stated in the reference letter. The Authority anticipates UE&C's final report in the near future. We will keep you informed until this report is submitted to you.

If you have any questions, please contact Mr. J. A. Gray, Jr. of my staff.

Very truly yours,

A handwritten signature in cursive script, appearing to read "J. P. Bayne", with a small flourish at the end.

J. P. Bayne  
Executive Vice-President

cc: Resident Inspector  
U. S. Nuclear Regulatory Commission  
P. O. Box 136  
Lycoming, New York 13093