

USNRC REGION II
ATLANTA, GEORGIA
VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

83 SEP 23 P 5:20

W. L. STEWART
VICE PRESIDENT
NUCLEAR OPERATIONS

September 16, 1983

Mr. James P. O'Reilly
Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 2900
Atlanta, Georgia 30303

Serial No. 448
NO/JHL:acm
Docket Nos. 50-338
50-339
License Nos. NPF-4
NPF-7


Dear Mr. O'Reilly:

I. E. BULLETIN 83-06 NONCONFORMING
MATERIALS SUPPLIED BY TUBE-LINE
CORPORATION FACILITIES

A review of the information supplied by I. E. Bulletin 83-06 has been completed and indicates that there were no Tube-Line materials furnished for use in safety-related systems.

In addition, there were no further general concerns identified as a result of this review.

Very truly yours,


W. L. Stewart

cc: Mr. James R. Miller, Chief
Operating Reactors Branch No. 3
Division of Licensing

Mr. Richard C. DeYoung
Office of Inspection and Enforcement
Washington, D. C. 20555

Mr. M. B. Shymlock
NRC Resident Inspector
North Anna Power Station

8310040550 830916
PDR ADOCK 05000338
Q PDR

110
IE11