

WOLF CREEK

NUCLEAR OPERATING CORPORATION

Neil S. "Buzz" Carns
Chairman, President and
Chief Executive Officer

January 26, 1995

WM 95-0005

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station P1-137
Washington, D. C. 20555


Subject: Docket No. 50-482: Inservice Inspection Summary
Report for the Seventh Refueling Outage

Gentlemen:

This letter provides the Inservice Inspection Summary Report for the seventh refueling outage at Wolf Creek Generating Station (WCGS). This report is being submitted in accordance with ASME Boiler and Pressure Vessel Code 1980 Edition through Winter 1981 Addenda, Section XI, Article IWA-6000, Paragraph 6230. Records and reports documenting the inspections are maintained at WCGS and are available for review upon request.

If you should have any questions regarding this submittal, please contact me at (316) 364-3831, extension 4000, or Mr. R. D. Flannigan at extension 4500.

Very truly yours,



Neil S. Carns

NSC/jra

Attachment

cc: L. J. Callan (NRC), w/a
D. D. Chamberlain (NRC), w/a
J. F. Ringwald (NRC), w/a
J. C. Stone (NRC), w/a

30000
9501310335 950126
PDR ADOCK 05000482
Q PDR

P.O. Box 411 / Burlington, KS 66839 / Phone: (316) 364-8831

An Equal Opportunity Employer M/F/HG/VET

AD47