



Nebraska Public Power District

GENERAL OFFICE
P.O. BOX 499, COLUMBUS, NEBRASKA 68601-0499
TELEPHONE (402) 564-8561

LQA8300229

October 6, 1983

50-298

Director of Nuclear Reactor Regulation
Attention: Mr. Domenic B. Vassallo, Chief
Operating Reactors Branch No. 2
Division of Licensing
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Vassallo:

Reference: 1) Telecon, J. Weaver (NPPD) to B. Siegal (NRC),
July 28, 1983, "Containment Penetration Splices
Final Report"

Subject: Containment Penetration Splice Repair
Cooper Nuclear Station

In accordance with the commitment made in Reference 1, this letter is written to inform you that splice repairs have been completed on all essential systems in Cooper Nuclear Station's drywell penetrations. The old tape and splices were removed and new splices, covered with environmentally-qualified heat shrinkable tubing, were installed to ensure system operability during normal, abnormal, and post-accident environments.

Quality Control and Quality Assurance measures were taken to ensure all work was performed properly and within applicable guidelines. Upon completion, all effected circuits were tested and verified for proper system operation.

If you have any further questions, please feel free to contact my office.

Sincerely,

J. M. Pilant
Technical Staff Manager

JMP/kcw:rs6/2

8310140190 831006
PDR ADOCK 05000278
PDR

A001
1/0