



**ENTERGY**

Entergy Operations, Inc.  
PO Box 8  
Biloxi, LA 70009  
Tel 504 739 6774

**R. F. Burski**

Director  
Nuclear Safety  
Waterford 3

W3F1-91-0336

A4.05

QA

Jun. 19, 1991

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D.C. 20555

Subject: Waterford 3 SES  
Docket No. 50-382  
License No. NPF-36  
Completion of GL 88-17 Hardware-Related Changes

Gentlemen:

In the December 11, 1990 NRC letter from D.L. Wigginton to R.P. Barkhurst regarding "Programmed Enhancements for Generic Letter (GL) 88-17", it was requested that Waterford 3 inform the NRC when GL 88-17 hardware-related modifications have been implemented and determined to be operational. The purpose of this letter is to provide the information requested in the December 11, 1990 letter.

The hardware-related modifications required by GL 88-17 were implemented and determined to be operational before the end of Refuel 4. The only remaining required GL 88-17 hardware-related modification to be completed during Refuel 4 was the implementation of the new level system, the Reactor Coolant Shutdown Level Measurement System (RCSLMS), which was implemented and was determined to be operational on May 14, 1991.

In addition, the hardware-related modifications associated with Technical Specification Change Request NPF-38-108 and issued in Amendment 65, removal of the automatic closure interlocks on the shutdown cooling suction valves, were completed and deemed operable during Refuel 4 on May 13, 1991.

Should you have any questions regarding this submittal, please contact Roy Prados at (504) 739-6632.

Very truly yours,

RFB/RWP/3c

cc: R.D. Martin, NRC Region IV, D.L. Wigginton, NRC-NRR, E.L. Blake,  
R.B. McGehee, N.S. Reynolds, NRC Resident Inspectors Office

9106240259 910619  
PDR ADOCK 05000382  
P PDR

A001  
1/0