

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

PHONE: (205) 729-0815

NRC USE ONLY

LER SUPPLEMENTAL INFORMATION

BFRO-50-260 / 83079 Technical Specification Involved 4.2.B

Reported Under Technical Specification 6.7.2.b(3) * Date Due NRC 1/11/84

Event Narrative:

Units 1 and 3 were in refueling outages. Unit 2 was operating normally at 91-percent power. Surveillance Instruction (SI) 4.2.B-1, "Instrumentation That Initiate or Control the CSCS, Reactor Low Water Level," LIS-3-58A and C, LITS-3-58B and D, LI-3-58A and B, was not performed within the maximum frequency interval specified in the technical specifications.

Surveillance Instruction 4.2.B-1 was listed on the surveillance schedule to be performed between November 24, 1983 and November 28, 1983. A notation was inadvertently made on a working copy of the schedule listing which indicated that the SI had been performed. This resulted in the failure to perform the instruction during the normal due date band. Surveillance Instruction 4.2.B-1 was satisfactorily performed on December 12, 1983. This is considered a random event and no further recurrence control is required. There was no effect on public health and safety.

* Previous Similar Events:

The following listing relates SIs not performed due to various personnel errors relating to scheduling: BFRO-50-259/80068, 82042, 82051, 83022, 83027. BFRO-50-260/81010, 82010.

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: JRP

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

January 10, 1984

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Suite 2900
101 Marietta Street, NW.
Atlanta, Georgia 30303


Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 - DOCKET
NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE OCCURRENCE
REPORT BFR0-50-260/83079

The enclosed report provides details concerning a surveillance instruction not performed within the allowable time band. This report is submitted in accordance with Browns Ferry unit 2 Technical Specification 6.7.2.b(3).

Very truly yours,

TENNESSEE VALLEY AUTHORITY


J. A. Coffey
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

NRC Inspector, Browns Ferry

OFFICIAL COPY

1622