




GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAumont, TEXAS 77704

AREA CODE 713 838-6631

January 11, 1984
RBG-16,746
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-155

Gulf States Utilities Company has not completed its investigation of DR-155 concerning personnel airlock seals supplied by W. J. Woolley Company. An interim or final status report will be provided by May 15, 1984.

Sincerely,

J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

WJB/PJD/mc

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

NRC Resident Inspector-Site

8401230276 840111
PDR ADOCK 05000458
S PDR

IE-27 1/0