




**GULF STATES UTILITIES COMPANY**

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

January 10, 1984  
RBG-16,744  
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region IV, Office of Inspection and Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011



Dear Mr. Collins:

River Bend Station Unit 1  
Docket No. 50-458  
Interim Report/DR-134

Gulf States Utilities Company has not completed its investigation of DR-134 concerning four lines located at the outlet of each residual heat removal system heat exchanger shell. An interim or final status report will be provided by February 23, 1984.

Sincerely,

*J. E. Booker*

J. E. Booker  
Manager-Engineering  
Nuclear Fuels & Licensing  
River Bend Nuclear Group

*WJB* & PJD  
WEB/PJD/mc

cc: Director of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

NRC Resident Inspector-Site

8401230522 840110  
PDR ADOCK 05000458  
S PDR

IE-2710