

SOUTH CAROLINA ELECTRIC & GAS COMPANY

POST OFFICE 764

COLUMBIA, SOUTH CAROLINA 29218

G. W. DIXON, JR.
VICE PRESIDENT
NUCLEAR OPERATIONS

January 5, 1984

Mr. James P. O'Reilly
Regional Administrator
U.S. Nuclear Regulatory Commission
Region II, Suite 2900
101 Marietta Street, N.W.
Atlanta, Georgia 30303

SUBJECT: Virgil C. Summer Nuclear Station
Docket No. 50/395
Operating License No. NPF-12
Notice of Violation
NRC Inspection Report 83-34

Dear Mr. O'Reilly:


South Carolina Electric and Gas Company (SCE&G) is in agreement with the alleged violation addressed in Appendix "A" of NRC Inspection Report 83-34.

As stated in the Report, SCE&G failed to have Alarm Response Procedures (ARP) for each of the Diesel Generators' (D/G) local control panels. The D/G alarms are either individually repeated or feed a common trouble alarm on the Main Control Board. Prior to the identification of the violation, the Licensee considered the Main Control Board ARPs, which responded to the D/G alarms, to adequately satisfy the procedural requirements of Regulatory Guide 1.33, Rev. 2, dated February 1978.

Diesel Generator local control panel ARPs are presently being developed. The procedures are expected to be issued by January 15, 1984. The development of these procedures are considered to be adequate to prevent further violation.

If there are any questions, please call at your convenience.

Very truly yours



O. W. Dixon, Jr.

CJM:OWD:mac

Distribution - Page Two

8401240331 840111
PDR ADOCK 05000395
G PDR

Mr. James P. O'Reilly
NRC Inspection Report 83-34
Page Two
January 5, 1984

Distribution

cc: V. C. Summer
T. C. Nichols, Jr./O. W. Dixon, Jr.
E. H. Crews, Jr.
E. C. Roberts
W. A. Williams, Jr.
D. A. Nauman
Group Managers
O. S. Bradham
C. A. Price
D. A. Lavigne
J. F. Heilman
C. L. Ligon (NSRC)
G. J. Braddick
D. J. Richards
NRC Res. Inspector
J. B. Knotts, Jr.
I&E (Washington)
Document Management
Branch
INPO Records Center
NPCF
File