

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
1750 Chestnut Street Tower II

February 28, 1983

83 MAR 2 9:50

REGION II
ATLANTA, GEORGIA

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303


Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE
REPORT BFRO-50-259/82013 - REVISION 3

The enclosed report is a supplement to my letters to you dated February 12, 1982, August 10, 1982, and October 29, 1982 concerning degraded voltage relays whose trip stepoint was found to be below the minimum allowable trip point setting. This report is submitted in accordance with Browns Ferry unit 1 Technical Specification 6.7.2.a(9).

Very truly yours,

TENNESSEE VALLEY AUTHORITY


H. J. Green
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

NRC Inspector, Browns Ferry

8303040558 830228
PDR ADOCK 05000259
S PDR

OFFICIAL COPY

TE 22

1983-TVA 50TH ANNIVERSARY

An Equal Opportunity Employer