



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET

P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

February 6, 1984

W3P84-0299
Q-3-A20.02.02
3-A1.01.04
L.02

Director of Nuclear Reactor Regulation
Attention: Mr. G.W. Knighton, Chief
Licensing Branch No. 3
Division of Licensing
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

SUBJECT: Waterford SES Unit 3
Docket No. 50-382
Response to Generic Letter 83-28, Item 4.5.1
Reactor Trip System Reliability (System Functional Testing)

Dear Sir:

By the referenced letter LP&L provided the initial response to Generic Letter 83-28. We indicated at that time that the requirements of Item 4.5.1, to provide for independent testing of the diverse (undervoltage and shunt) reactor trip features, would be included in plant procedures.

Operating Procedure OP-903-006, Manual Reactor Trip Test, has been revised to include the required functional testing of the diverse trip features.

Should you have any questions or comments in this matter please contact Mike Meisner at (504) 363-8938.

Yours very truly,

K. W. Cook
Nuclear Support & Licensing Manager

KWC/MJM/ch

cc: W.M. Stevenson, E.L. Blake, J. Wilson, G.L. Constable

8402100013 840206
PDR ADOCK 05000382
A PDR

A055
1/0