

UNION ELECTRIC COMPANY

1901 GRATIOT STREET
ST. LOUIS, MISSOURI

DONALD F. SCHNELL
VICE PRESIDENT

January 23, 1984

MAILING ADDRESS:
P. O. BOX 149
ST. LOUIS, MISSOURI 63166

Mr. C. J. Paperiello
Emergency Preparedness and
Radiological Safety Branch
U.S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr. Paperiello:

ULNRC-737

INSPECTION REPORT NO. 50-483/83-30 (DRMSP)

This reply is in response to your letter of January 9, 1984 which transmitted the report of the inspection conducted at Callaway Plant, Unit 1 during the period of December 13, 1983 to December 15, 1983. Our response to the open item listed within the body of Inspection Report Number 50-483/83-30 (DRMSP) is presented below.

None of the material in the inspection report or in this response is considered proprietary by Union Electric Company.

(50-483/83-07-05) OPEN ITEM


Finalize procedure QS-22 defining REMP management responsibilities. This procedure is under review by the licensee's management and has not been approved as yet. This item will remain open, pending licensee approval of this procedure.

RESPONSE

Please find enclosed the approved procedure QS-22 titled "Radiological Environmental Monitoring Program."

If you have any questions regarding this response or if additional information is required, please let me know.

Very truly yours,


Donald F. Schnell

BFH/lw
Enclosures

cc: Dr. M. J. Oestmann, NRC Region III
Mr. J. E. Konklin, NRC Region III
NRC Resident Inspector, Callaway Plant
Missouri Public Service Commission

8402130370 840208
PDR ADQCK 05000482

FEB 3 1984