

RECEIVED
NRC

Arizona Public Service Company

P.O. BOX 21666 • PHOENIX, ARIZONA 85036

JAN 30 AM 8:50

REGION V FILE

January 23, 1984
ANPP-28662-BSK/TRB

U. S. Nuclear Regulatory Commission
Region V
Creskide Oaks Office Park
1450 Maria Lane - Suite 210
Walnut Creek, CA 94596-5360

Attention: Mr. T. W. Bishop, Director
Division of Resident
Reactor Projects and Engineering Programs

Subject: Time Extension For Report - DER 83-72
A 50.55(e) Potentially Reportable Deficiency Relating To
Undersized Welds In Unmit 1 Auxiliary Building Discovered By
NRC CAT Team
File: 84-019-026; D.4.33.2

Reference: (A) Telephone conversation between P. Narbut and R. Tucker on
October 26, 1983
(B) ANPP-28287, dated November 28, 1983 (Interim Report)

Dear Sir:

The NRC was notified of a potentially reportable deficiency in
Reference (A), and an Interim Report was transmitted by Reference (B).
At that time, it was estimated that a Final Report would be available by
January 27, 1984.

Due to the extensive investigation and evaluation required, it is now
expected that this information will be finalized by February 29, 1984, at
which time a complete report will be submitted.

There is no new information or change to the Interim Report at this time.

Very truly yours,

E. E. Van Brunt

E. E. Van Brunt, Jr.
AFS Vice President, Nuclear
ANPP Project Director

EEVB/TRB:ru

cc: See Page Two

8402130385 840123
PDR ADOCK 05000528
S PDR

IE-27 110

Mr. T. W. Bishop
DER 83-72
Page Two

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.
J. A. Roedel
D. B. Fasnacht
A. C. Rogers
B. S. Kaplan
W. E. Ide
J. Vorees
J. R. Dynum
P. P. Klute
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
H. Foster
D. R. Hawkinson
L. E. Vorderbrueggen
G. A. Fiorelli
S. R. Frost
J. Self
D. Canady

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, GA 30339