

U.S. NUCLEAR REGULATORY COMMISSION
LICENSEE EVENT REPORTAPPROVED BY OMS
3130-0011
EXPIRES 4-30-82

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N C M G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CONT

01 REPORT SOURCE L 6 0 5 0 0 0 3 6 9 7 0 5 0 6 8 3 3 0 9 2 8 8 3 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On 8/29/83, a surveillance test review determined that the monthly surveillance
03 test on the Reactor Coolant System cold leg accumulator pressure had not been per-
04 formed within the required time interval (4/28/83 + 7 day grace period = 5/5/83)
05 as specified by T.S.4.5.1.1.2a. This is reportable pursuant to T.S.6.9.1.11(c).
06 The test was successfully completed 8 days after the extended due date which
07 indicates that the accumulators could have performed their required function had
08 a LOCA occurred. Health and safety of the public were unaffected.

09 SYSTEM CODE S F 11 CAUSE CODE A 12 CAUSE SUBCODE X 13 COMPONENT CODE Z Z Z Z Z Z Z 14 Z 15 Z 16
17 LER/RO REPORT NUMBER 8 3 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 This event is attributed to Personnel Error because the "complete by" date entered
11 on the periodic tests scheduling program was based on a date from the document
12 information retrieval system (which contained the date the previous work request
13 was signed off) rather than the date the previous testing was actually performed.
14 In the future the periodic test scheduling program will be updated from work re-
15 quests only.

16 FACILITY STATUS X 28 0 0 0 29 Mode 3 30 METHOD OF DISCOVERY C 31 DISCOVERY DESCRIPTION 32 Surveillance Test Review
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

17 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 NA 35 AMOUNT OF ACTIVITY NA 36 LOCATION OF RELEASE NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

18 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

19 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

20 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

21 PUBLICITY ISSUED DESCRIPTION N 44 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

NAME OF PREPARER Phillip B. Nardoci

PHONE (704) 373-7432

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

September 28, 1983

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

83 SEP 30
83 OCT 3 49:28

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street NW, Suite 2900
Atlanta, Georgia 30303

Subject: McGuire Nuclear Station Unit 1
Docket No. 50-369
LER/RO-369/83-73

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/83-73. This report concerns T.S. 4.5.1.1.2, "Each Cold Leg Injection Accumulator Water Level and Pressure Channel Shall be Demonstrated Operable: a. At Least Once Per 31 Days by the Performance of an Analog Channel Operational Test,...". This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

Hal B. Tucker
Hal B. Tucker *by PHB*

PBN:jfw
Attachment

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. W. T. Orders
NRC Resident Inspector
McGuire Nuclear Station

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

OFFICIAL COPY
IE 22
1/1