

# CP&L

Carolina Power & Light Company

USNRC REGION II  
ATLANTA, GEORGIA

H. B. ROBINSON STEAM ELECTRIC PLANT  
POST OFFICE BOX 790  
HARTSVILLE, SOUTH CAROLINA 29550

93 OCT 4 All: 22

SEP 29 1983

Robinson File No: 13510C

Serial: RSEP/83-1247

Mr. James P. O'Reilly  
Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, N. W., Suite 3100  
Atlanta, Georgia 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2  
DOCKET NO. 50-261/  
LICENSE NO. DPR-23  
PROMPT NOTIFICATION - HVH COOLER LEAK


Dear Mr. O'Reilly:

In accordance with Plant Technical Specification 6.9.2.a.3, the following event is reported.

At 2230 hours on September 28, 1983, a service water leak was discovered on Containment Fan Cooler HVH-2. At 2244 hours, the HVH-2 leak was isolated. The NRC was notified of this Unusual Event and of its termination via the Emergency Notification System (ENS) at 2244 hours. In accordance with Technical Specification 3.3.2.2.a, operability testing of the containment spray pumps was completed at 0230 hours. This event is considered a degradation of a containment boundary pursuant to IE Bulletin 80-24 and is reported as such.

This event was reported to Mr. G. P. Beatty, Jr., Manager - Robinson Nuclear Project Department, on September 28, 1983, and to NRC Region II on September 29, 1983.

Very truly yours,



R. E. Morgan  
General Manager  
H. B. Robinson SEG Plant

CLW:CWC/bss

cc: G. P. Beatty, Jr.  
S. P. Weise

OFFICIAL COPY

8310070308 830929  
PDR ADOCK 05000261  
S PDR

IE 22  
1/0