



Docket No. 50-346

License No. NPF-3

Serial No. 1026

February 17, 1984

RICHARD P. CROUSE
Vice President
Nuclear
(419) 259-5221

Director of Nuclear Reactor Regulation
Attention: Mr. John F. Stolz
Operating Reactor Branch No. 4
Division of Operating Reactors
United States Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Stolz:

This letter is being submitted to correct an error in our letter dated January 17, 1984 (Serial No. 1021). In attachment 1 of that letter the Containment Design Pressure was given as 47 psig and it should be 36 psig as indicated in the FSAR. This difference in pressure has no effect on the conclusion of the evaluation contained in Attachment 1 for the Davis-Besse Nuclear Power Station Unit No. 1.

Very truly yours,

RPC:GAB:lah

cc: DB-1 NRC Resident Inspector

8402240014 840217
PDR ADOCK 05000346
P PDR

Acc 1/10