




LOUISIANA / 142 DELARONDE STREET
POWER & LIGHT P. O. BOX 6008 NEW ORLEANS, LOUISIANA 70174

February 15, 1984

W3K84-0326
Q-3-A35.07.57



Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

REFERENCE: LP&L letter W3K83-1549 dated October 13, 1983

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 57
"Inadequate Instrumentation and Control Installations and Turnover
Documentation"
Seventh Interim Report

The above referenced letter indicated submittal of the Final Report to the
USNRC on February 15, 1984.

At the present time, final review of corrective action documentation is
ongoing and is expected to be completed on March 30, 1984. The Final Report
will be submitted to the USNRC on April 6, 1984.

Very truly yours,

T. F. Gerrets
Corporate Quality Assurance Manager

TFG:CNH:JC

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8402280292 840215
PDR ADOCK 05000382
S PDR

IE-271/0

Mr. John T. Collins
February 15, 1984
W3K84-0326
Page 2

cc: Mr. E. L. Blake
Shaw, Pittman, Potts, & Trowbridge
1800 M Street, N.W.
Washington, D.C. 20036

Mr. W. M. Stevenson
Monroe & Lemann
1424 Whitney Building
New Orleans, Louisiana 70130