

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401  
400 Chestnut Street Tower II

January 31, 1984

U.S. Nuclear Regulatory Commission  
Region II  
Attn: Mr. James P. O'Reilly, Regional Administrator  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNITS 1 AND 2 - NRC-OIE REGION II INSPECTION REPORT  
50-327/83-13 AND 50-328/83-13

The following information concerns OIE inspection report Nos. 50-327/83-13 and 50-328/83-13 and the TVA response submitted to you from D. S. Kammer on October 14, 1983. TVA's response to deficiency 327,328/83-13-08 committed TVA to revise the Sequoyah emergency monitoring implementing procedures and the Muscle Shoals Emergency Center emergency monitoring implementing procedures by January 31, 1984.


In order to maintain consistency between TVA's other nuclear plants, we are also revising the Browns Ferry and Watts Bar procedures. For this reason, our completion date for the revision to the emergency monitoring procedures is now March 30, 1984.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2676.

To the best of my knowledge, I declare the statements contained herein are complete and true.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



L. M. Mills, Manager  
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339

8402280528 840217  
PDR ADOCK 05000327  
G PDR