

THE CINCINNATI GAS & ELECTRIC COMPANY



CINCINNATI, OHIO 45201

October 10, 1983

LOZ-83-0185

J. WILLIAMS, JR
SENIOR VICE PRESIDENT
NUCLEAR OPERATIONS

Docket No. 50-358

U.S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Attention: Mr. J.G. Keppler
Regional Administrator

Gentlemen:

RE: WM. H. ZIMMER NUCLEAR POWER STATION - UNIT 1
10CFR50.55(e), ITEM E-53, 4.16KV SWITCHGEAR
WIRING DIAGRAM DISCREPANCIES
W.O. 57300, JOB E-5590, FILE NO. 956C, E-53

This letter constitutes an interim report concerning the subject condition initially reported to the Commission on September 22, 1983 as a potentially reportable deficiency under the requirements of 10CFR50.55(e).

CG&E has been reviewing prior Nonconformance Reports (NR's) in the Quality Confirmation Program and other quality reviews. These reviews occasionally identify conditions which occurred years ago and which may have represented significant deficiencies that were reportable under the requirements of 10CFR50.55(e). In response to 10CFR50.55(e) Item E-44, CG&E committed to identify such significant deficiencies found in these reviews.


The condition described in this report was found in a review of H.J. Kaiser voided NR's E-456 and E-487 dated June 4, 1976 and June 15, 1976 respectively. These NR's identified that wiring diagrams for 4160 Volt Division I switchgear contained errors that resulted in field deficiencies. CG&E has reviewed the two NR's and identified a total of seventy (70) discrepancies. These discrepancies are under evaluation to determine their impact on the safety of plant operations and any required corrective actions. A follow-up report detailing the results of this evaluation will be submitted by January 20, 1984.

Mr. J.G. Keppler
Regional Administrator
October 10, 1983
LOZ-83-0185
Page 2

We trust the above will be found acceptable as an interim report under 10CFR50.55(e).

Very truly yours,

THE CINCINNATI GAS & ELECTRIC COMPANY

By 
J. WILLIAMS, JR.
SENIOR VICE PRESIDENT

DJS/sfr

cc: NRC Office of Inspection & Enforcement
Washington, D.C. 20555
NRC Resident Site Supervisor
ATTN: W.M. Hill
NRC Zimmer Project Inspector, Region III
ATTN: E. R. Schweibinz