



DmB



Northern States Power Company

414 Nicollet Mall  
Minneapolis, Minnesota 55401  
Telephone (612) 330-5500

November 18, 1983

Mr. James G. Keppler  
Regional Administrator - III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Dear Mr. Keppler:

PRAIRIE ISLAND NUCLEAR GENERATING PLANT  
Docket No. 50-282 License No. DPR-42  
Docket No. 50-306 License No. DPR-60

In response to IE Bulletin 83-06, the following is offered:

A check was made of purchase order records (1981 to present) to determine if any material was purchased from any of the companies listed in Attachments 2 and 3 of the Bulletin. When the check revealed purchase orders issued to these companies, receipt inspection paperwork was reviewed to determine if any of the received material was supplied by Tube-Line. The results of this review show that no Tube-Line supplied materials have been furnished for Prairie Island.

About 50 manhours were expended in evaluating and responding to this Bulletin.

Sincerely,

C.E. Larson  
Director, Nuclear Generation

cc: G. Charnoff  
C. Feierabend

8312020342 831118  
PDR ADDCK 05000282  
Q PDR

NOV 21 1983  
IE// 1/0