


**LOUISIANA**

POWER & LIGHT/Waterford 3 SES/P. O. Box B/Killona, LA 70066

November 22, 1983

W3K83-1831  
Q-3-A35.07.81



Mr. John T. Collins  
Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012

REFERENCE: LP&L Letter W3I83-0292 dated August 30, 1983

Dear Mr. Collins:


SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 81  
"Shelf Life Exceeded on Cable Splice and Termination Tape"  
Fourth Interim Report

The above referenced letter indicated submittal of a Final Report to the USNRC no later than November 25, 1983.

At the present time, a review of the test results submitted by the Okonite Company is scheduled to be completed in early December 1983.

A Final Report will be submitted to the USNRC on December 15, 1983.

Very truly yours,

  
T. F. Gerrets  
Quality Assurance Manager

TFG:CNH:SSTG

cc: Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

8312090059 831122  
PDR ADOCK 05000382  
S PDR

IE-27  
1/0

Mr. John T. Collins  
November 22, 1983  
W3K83-1831  
Page 2

cc: Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. E. L. Blake  
Shaw, Pittman, Potts, & Trowbridge  
1800 M Street, N.W.  
Washington, D.C. 20036

Mr. W. M. Stevenson  
Monroe & Lemann  
1424 Whitney Building  
New Orleans, Louisiana 70130