

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M I D C C 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 1 5

CON'T

01 L 6 0 5 0 0 0 3 1 5 7 1 1 0 3 8 3 5 1 2 0 1 8 3 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

012 | NUMBER 2 STEAM GENERATOR BLOWDOWN ISOLATION VALVE, DCR-320, INDICATION REMAINED IN THE
013 | MID-POSITION FOLLOWING FUNCTIONAL TRIP CHECK OF THE STEAM GENERATOR BLOWDOWN TREATMENT
014 | MONITOR. DCR-320 WAS REMOVED FROM SERVICE FOR REPAIR. THIS EVENT WAS NON-CONSERVATIVE
015 | WITH RESPECT TO TECHNICAL SPECIFICATION 3.6.3.1 TABLE 3.6-1 ITEM A.18. THE ACTION
016 | REQUIREMENTS WERE MET. PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED. SIMILAR OCCURENCE
017 | INCLUDES: 50-315/83-072.

018 S D 11 E 12 B 13 V A L V E X 14 D 15 Z 16

17 8 3 1 1 2 0 3 L 0

A 13 Z 19 Z 20 Z 21 0 0 0 0 N 23 N 24 A 25 H 0 3 5

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

110 | DURING INVESTIGATION OF DCR-320, THE STEM COUPLING BOLT, WHICH HOLDS THE LIMIT SWITCH
111 | ACTUATION YOKE WAS SHEARED, THUS CAUSING THE VALVE INDICATION TO REMAIN IN THE MID-
112 | POSITION. THE STEM COUPLING AND BOLT WERE REPLACED: DCR-320 TESTED SATISFACTORILY
113 | AND WAS RETURNED TO SERVICE.

115 E 28 0 9 5 29 NA 30 B 31 OPERATOR OBSERVATION 32

116 Z 33 Z 34 NA 35 NA 36

117 0 0 0 37 Z 38 NA 39

118 0 0 0 40 NA 41

119 Z 42 NA 43

120 N 44 NA 45

IE22

8312090259 831201
PDR ADOCK 05000315
S PDR

NRC USE ONLY

NAME OF PREPARER R. A. PALMER

(616)465-5901

DmB



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

December 1, 1983

Mr. J.G. Keppler, Regional Administrator
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137


Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications, the following report/s are submitted:

RO 83-112/03L-0

Sincerely,


W.G. Smith, Jr.
Plant Manager

/cbm

Attachment

cc: John E. Dolan
M.P. Alexich
R.F. Kroeger
H. Brugger
E.R. Swanson, RO:III
R.C. Callen, MPSC
G. Charnoff, Esq.
J.M. Hennigan
R.O. Bruggee, EPRI
INPO
PNSRC
J.F. Stietzel
E.L. Townley
Dir., IE (30 copies)
Dir., MIPC (3 copies)

DEC - 5 1983

1/1 FE22