

CONTROL BLOCK: | | | | | | | ① (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

PHONE: 612 388-1121



DmB

Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

December 2, 1983

Regional Administrator
Region III
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-282 License No. DPR-42

Inoperability of Diesel Cooling Water Pump No. 22

The License Event Report for this occurrence is attached.

This event is reported in compliance with Technical Specification 6.7.B.2.(b), since it represents operation in a degraded mode permitted by a limiting condition for operation.

for Thomas Musolf

David Musolf
Manager - Nuclear Support Services

DMM/TMP/bd

cc: NRC Document Control Desk (1)
NRC Resident Inspector
MPCA
Attn: J W Ferman

Attachment

DEC 5 1983
IF22 1/1