

**GULF STATES UTILITIES COMPANY**

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 409 838-6631




November 23, 1983

RBG-16,422

File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region IV, Office of Inspection and Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011



Dear Mr. Collins:

River Bend Station Unit 1  
Docket No. 50-458  
Interim Report/DR-134

Gulf States Utilities Company has not completed its investigation of DR-134 concerning four lines located at the outlet of each residual heat removal system heat exchanger shell. An interim or final status report will be provided by January 10, 1984.

Sincerely,

*William J. Booker*  
for J. E. Booker  
Manager-Engineering,  
Nuclear Fuels & Licensing  
River Bend Nuclear Group

PJD  
JEB/PJD/kt

cc: Director of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

NRC Resident Inspector-Site

8312150161 831123  
PDR ADOCK C5000458  
S PDR

IE27

110