

PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET

P.O. BOX 8699

PHILADELPHIA, PA. 19101

(215) 841-4502

JOHN S. KEMPER
VICE-PRESIDENT
ENGINEERING AND RESEARCH

December 7, 1983

Mr. Thomas E. Murley, Director
United States Nuclear Regulatory Commission
Office of Inspection and Enforcement, Region I
631 Park Avenue
King of Prussia, PA 19406

Subject: Significant Deficiency Report No. 90
Comsip, Inc. Containment Gas Analyzers
Limerick Generating Station, Units 1 and 2

Attachment: Letters Comsip, Inc. to USNRC dated April 13, 1983
File: QUAL 2-10-2 (SDR #90)

Dear Mr. Murley:

The attached letter has brought to our attention a deficiency in the Comsip, Inc. Containment Gas Analyzers concerning catalyst bed configuration on this equipment. This deficiency has been previously reported to the USNRC under the provisions of 10CFR, Part 21.

We consider the deficiency described in the Attachment as a significant deficiency per 10CFR50.55(e) and are hereby notifying you as required.

We believe that the Comsip, Inc. report submitted under the provisions of 10CFR, Part 21 provides the information required for 10CFR50.55(e) reporting. Therefore, we anticipate that this letter will be our only report to you on this subject.

We will of course assure that the defective equipment is corrected in accordance with the instructions received from the vendor.

Sincerely,

John S. Kemper

JPE/drd/831202-1

Attachment

Copy to: Director of Inspection and Enforcement
United States Nuclear Regulatory Commission
Washington, DC 20555

S. K. Chaudhary, USNRC Resident Inspector

8312200251 831207
PDR ADOCK 05000352
S PDR

IE27
11