

Georgia Power Company  
333 Piedmont Avenue  
Atlanta, Georgia 30308  
Telephone 404 526-7893

Mailing Address:  
Post Office Box 4545  
Atlanta, Georgia 30302

USNRC REGION II  
ATLANTA, GEORGIA

03 DEC 13 P 4:22

G. F. Head  
Senior Vice President  
Power Generation

*the southern electric system*

NED-83-584

November 21, 1983

U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II - Suite 2900  
101 Marietta Street, NW  
Atlanta, Georgia 30303

REFERENCE:  
RII: JPO  
50-321/50-366  
I&E Bulletin  
83-06

ATTENTION: Mr. James P. O'Reilly

GENTLEMEN:

Georgia Power Company submits the following information in response to IEB 83-06, concerning nonconforming materials supplied by Tube-Line Corporation.

In response to Action Item 1 of the reference bulletin, we have reviewed the lists of purchasing and receiving companies given in Attachments 2 and 3 to the bulletin. This review disclosed that Tube-Line materials have been furnished for use at Plant Hatch.

Action Item 2.a. requested, for operating plants, a list of Tube-Line materials which are not yet installed in safety-related systems. The following response is provided:

Consolidated Pipe and Supply provided the following materials:

- ( 1) 8"x16" stainless steel reducer
- ( 1) 10"x18" stainless steel reducer

Capitol Pipe and Steel provided the following materials:

- ( 1) Piece 6"x3" 540 LR 90 degree elbow SA234 WPB heat code #EGX
- (12) Pieces 4" 540 CAP SA234 WPB heat code #EUYC

HUB Incorporated provided the following materials:

- ( 4) Pieces 10" SCH 10 LR 90 degree elbow WP304-W

Action Item 2.a. further requested identification of safety-related systems in which these materials would be installed. None of the materials listed above will be used in safety-related systems. All items have been placed under a quality control hold and will be evaluated for use in nonsafety-related systems only.

Action Items 2.b. and 2.c. require no response since no Tube-Line materials will be installed in safety-related systems.

8312200395 831121  
PDR ADOCK 05000321  
G PDR

*12/1/83*

U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
November 21, 1983  
Page 2


Action Item 3.a. requested a list of Tube-Line materials that had previously been installed in safety-related systems. One such item was provided by Capitol Pipe and Steel and installed in the Plant Service Water (PSW) System in the strainer backwash system located at the intake structure. This was a 6"x3" 540 LF 90 degree elbow SA234 heat code #EGX.

Pursuant to Action Item 3.b., an evaluation was performed to determine the suitability of installed Tube-Line materials for intended service. The result of our evaluation was, for this particular installation in the PSW strainer backwash system, that no safety or operability problems would be posed by allowing the material to remain in place.


This completes our response to IEB 83-06. Please contact this office if further information is required.

G. F. Head states that he is Vice President of Georgia Power Company and is authorized to execute this oath on behalf of Georgia Power Company, and that to the best of his knowledge and belief the facts set forth in this letter are true.

GEORGIA POWER COMPANY

By:   
G. F. Head

Sworn to and subscribed before me this 21st day of November, 1983.

  
Notary Public

REB/rb

Enclosure

Notary Public, Georgia, State at Large  
My Commission Expires July 26, 1985

xc: H. C. Nix, Jr.  
Senior Resident Inspector  
Document Control Desk (NRC-Washington)