




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

December 15, 1983

W3K83-1978
Q-3-A35.07.81



Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

REFERENCE: LP&L letter W3K83-1831 dated November 22, 1983

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 81
"Shelf Life Exceeded on Cable Splice and Termination Tape"
Fifth Interim Report

The above referenced letter indicated submittal of a Final Report to the USNRC on December 15, 1983.

At the present time, supporting documentation and disposition of out of date material is being verified.

A Final Report will be submitted to the USNRC on January 13, 1984.

Very truly yours,

T. F. Gerrets
T. F. Gerrets
Quality Assurance Manager

TFG:CNH:VBR

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8401030067 831215
PDR ADOCK 05000382
S PDR

11
IE-27

Mr. John T. Collins
December 15, 1983
W3K83-1978
Page 2

cc: Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. E. L. Blake
Shaw, Pittman, Potts, & Trowbridge
1800 M Street, N.W.
Washington, D.C. 20036

Mr. W. M. Stevenson
Monroe & Lemann
1424 Whitney Building
New Orleans, Louisiana 70130