

ILLINOIS POWER COMPANY



U-0681  
0210.6-L  
N88-83(12-22)-L

CLINTON POWER STATION, P.O. BOX 678, CLINTON, ILLINOIS 61727

December 22, 1983

Docket No. 50-461

Mr. James G. Keppler  
Regional Administrator, Region III  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Subject: 10CFR Part 21 Defect  
Electroswitch Series 20K Control Switches

Dear Mr. Keppler:

Our letter of April 7, 1983 indicated that we expected to complete the replacement of the safety related Electroswitch Series 20K switches by December 31, 1983. Due to unexpected delays in procurement of the replacement switches, we now expect to have the engineering and the procurement completed by April 1, 1984. At that time we will begin the physical replacement of the switches on panel-by-panel basis. Replacement of the switches will be coordinated with the control room testing and completed prior to turn-over of the safety systems.

Sincerely yours,

D. P. Hall  
Vice President

JPO/ljb

cc: G. A. Harrison, NRC Clinton Licensing Project Manager  
NRC Resident Office  
Illinois Department of Nuclear Safety

8401050669 831222  
PDR ADOCK 05000461  
S PDR

DEC 30 1983

IE19 1/0