



GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704


AREA CODE 409 838 6831

December 28, 1983
RBG- 16,650
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Final Report/DR-122



Gulf States Utilities Company has completed its investigation of DR-122 concerning the filler material in B. F. Shaw shop welds and has determined that this condition is not reportable under 10CFR50.55(e).

Sincerely,

for J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

PJD
JEB/PJD/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

NRC Resident Inspector-Site

8401100450 831228
PDR ADOCK 05000458
S PDR

IE-27

1/0