

**GULF STATES UTILITIES COMPANY**


POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 409 838-6831



January 5, 1984  
RBG- 16,710  
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region IV, Office of Inspection and Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011



Dear Mr. Collins:

River Bend Station Unit 1  
Docket No. 50-458  
Final Report/DR-105

Gulf States Utilities Company has completed its investigation of DR-105 concerning the electrical separation between the Reactor Protection System and the Nuclear Steam Supply Shutoff wiring within the Power Generation Control Complex and determined this condition is not reportable under 10CFR50.55(e).

Sincerely,

*J. E. Booker*

J. E. Booker  
Manager-Engineering,  
Nuclear Fuels & Licensing  
River Bend Nuclear Group

*JEB*  
JEB/PJD/kt

cc: Director of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

NRC Resident Inspector-Site

8401130072 840105  
PDR ADOCK 05000458  
S PDR

IE-271/0