

Arizona Public Service Company

P.O. BOX 21666 • PHOENIX, ARIZONA 85036

RECEIVED
JAN 10 1984

January 3, 1984
ANPP-28538-ESK/TRB

U. S. Nuclear Regulatory Commission
Region V
Creekside Oaks Office Park
1450 Maria Lane - Suite 210
Walnut Creek, CA 94596-5368

Attention: Mr. T. W. Bishop, Director
Division of Resident
Reactor Projects and Engineering Programs

Subject: Time Extension For Report - DER 83-73
A 50.55(e) Potentially Reportable Deficiency Relating To
Unqualified Foxboro Power Supplies Were Installed In IE
Instrumentation Cabinets.
File: 84-019-026; D.4.33.2

Reference: (A) Telephone conversation between P. Narbut and R. Tucker
on October 27, 1983.
(B) ANPP-28290, dated November 28, 1983 (Interim Report)

Dear Sir:

The NRC was notified of a potentially reportable deficiency in
Reference (A), and an Interim Report was transmitted by Reference (B).
At that time, it was estimated that a Final Report would be available by
January 5, 1984.

Due to the extensive investigation and evaluation required, it is now
expected that this information will be finalized by March 2, 1984, at
which time a complete report will be submitted.

There is no new information or change to the Interim Report at this time.

Very truly yours,



E. E. Van Brunt, Jr.
APS Vice President
Nuclear Projects Management
ANPP Project Director

EFVB/TRB:ru

cc: See Page Two

8401160272 840103
PDR ADOCK 05000528
S PDR

IE27
110

Mr. T. W. Bishop

DER 83-73

Page Two

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.
G. C. Andognini
J. A. Roedel
D. B. Fasnacht
A. C. Rogers
B. S. Kaplan
W. F. Ide
J. Vorees
J. R. Bynum
D. D. Green
P. P. Klute
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
R. M. Grant
D. R. Hawkinson
L. E. Vorderbrueggen
G. A. Fiorelli
S. R. Frost
J. Self
D. Canady

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, GA 30339