



THE CLEVELAND ELECTRIC ILLUMINATING COMPANY

P.O. BOX 5000 - CLEVELAND, OHIO 44101 - TELEPHONE (216) 622-9800 - ILLUMINATING BLDG. - 55 PUBLIC SQUARE

*Serving The Best Location in the Nation*

MURRAY R. EDELMAN

VICE PRESIDENT  
NUCLEAR

December 21, 1983

Mr. James G. Keppler  
Regional Administrator, Region III  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

RE: Perry Nuclear Power Plant  
Docket Nos. 50-440; 50-441  
Cooling of the Reactor Core  
Isolation Cooling Room [RDC 72(83)]

Dear Mr. Keppler:

Our interim report dated August 16, 1983, concerning cooling of the Reactor Core Isolation Cooling (RCIC) room during a Loss of Coolant Accident (LOCA) stated that corrective action including the review of Safety Systems, design modifications, and the implementation of the modifications would be completed by March 24, 1984.

The review of Safety Systems is complete. We now anticipate that we will complete the design modifications by February 15, 1984, and implement the modifications by May 31, 1984.

Please call if there are additional questions.

Sincerely,

8401050326 831221  
PDR ADCK 05000440  
S PDR

Murray R. Edelman  
Vice President  
Nuclear Group

MRE:pab

cc: Mr. M. L. Gildner  
NRC Site Office

Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

U.S. Nuclear Regulatory Commission  
c/o Document Management Branch  
Washington, D.C. 20555

Records Center, SEF-IN  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339

DEC 27 1983

IE 27/10