




**Public Service Company of Colorado**

2420 W. 26th Avenue, Suite 100D Denver, Colorado 80211

50267

December 21, 1983  
Fort St. Vrain  
Unit No. 1  
P-83409

Mr. John T. Collins, Regional Administrator  
Region IV  
Nuclear Regulatory Commission  
611 Ryan Plaza Drive  
Suite 1000  
Arlington, Texas 76011



DOCKET NO.: 50-267

SUBJECT: Response to IE Bulletin 83-07

Dear Mr. Collins:

In response to IE Bulletin 83-07 dated July 22, 1983, Public Service Company of Colorado (PSC) has performed a thorough search of our records and has determined that even though we have purchased numerous items from many of the vendors shown, none of the materials designated for use at Fort St. Vrain came directly from or through Ray Miller, Inc. This search covered materials for use in safety related and non-safety related applications in addition to materials in stock at Fort St. Vrain Nuclear Generating Station.

Very truly yours,

*Lavene Brey*

H. L. Brey, Manager  
Nuclear Engineering Division

HLB/FT:pa

cc: U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

H005  
110