



GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704


AREA CODE 409 838 5931

April 6, 1984
RBG- 17519
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-110



Gulf States Utilities Company has not completed its investigation of DR-110 concerning an ultrasonic couplant that did not meet chemical analysis requirements. An interim or final status report will be provided by May 16, 1984.

Sincerely,

L. G. England Jr.

J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

JEB/PJD/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

NRC Resident Inspector-Site

B404170220 B40406
PDR ADOCK 05000458
S PDR

IE-27

110