

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 I L D R S 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 37 CAT 38

CON'T
01 REPORT SOURCE L 0 5 0 0 0 2 3 7 0 1 0 1 8 3 0 1 1 8 8 3 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

02 While performing a routine inspection during normal unit operation, a cracked weld
03 was found at the 2D2 feedwater heater emergency spill to normal heater drain line
04 connection (T.S.6.6.B.2.d). The event was of minimal safety significance since all
05 leakage was contained in the Turbine Building Floor Drain System. There was no
06 effect on public health or safety. Previous occurrences on Unit 2 reported by R.O.
07 82-35/03L-0, 82-55/03L-0, 82-57/03L-0 on Docket 050-237.

08
09
SYSTEM CODE C H 11
CAUSE CODE E 12
CAUSE SUBCODE B 13
COMPONENT CODE P I P E X X 14
COMP. SUBCODE C 15
VALVE SUBCODE Z 16
LER/RO REPORT NUMBER 17
EVENT YEAR 8 3 21 22
SEQUENTIAL REPORT NO. 0 0 1 24 25
OCCURRENCE CODE 0 3 28 29
REPORT TYPE L 30
REVISION NO. 0 32
ACTION TAKEN Z 18
FUTURE ACTION F 19
EFFECT ON PLANT Z 20
SHUTDOWN METHOD Z 21
HOURS 0 0 0 0 37 40
ATTACHMENT SUBMITTED N 23
NPR-4 FORM SUB. N 24
PRIME COMP. SUPPLIER N 25
COMPONENT MANUFACTURER G 0 8 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

10 The cracked weld is believed to be caused by excessive movement of the 2D2 feed-
11 water heater normal drain line. Modification M12-2-82-37 has been initiated to add
12 restraints to the D feedwater heater drain system during the upcoming refuel outage.
13 The weld repair will be made during this period.

14
15 FACILITY STATUS E 28
% POWER 0 5 5 29
OTHER STATUS N/A 30
METHOD OF DISCOVERY A 31
DISCOVERY DESCRIPTION Observation by Shift Foreman 32

16 RELEASED OF RELEASE Z 33
CONTENT Z 34
AMOUNT OF ACTIVITY N/A 35
LOCATION OF RELEASE N/A 36

17 PERSONNEL EXPOSURES
NUMBER 0 0 0 37
TYPE Z 38
DESCRIPTION N/A 39

18 PERSONNEL INJURIES
NUMBER 0 0 0 40
DESCRIPTION N/A 41

19 LOSS OF OR DAMAGE TO FACILITY
TYPE Z 42
DESCRIPTION N/A 43

20 PUBLICITY
ISSUED N 44
DESCRIPTION 8302010152 830118
PDR ADOCK 05000237
S PDR
NRC USE ONLY
85 86 87 88 89 90

NAME OF PREPARER B. Christel

PHONE: 815-942-2920, X-421