




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

April 5, 1984

W3K84-0817
Q-3-A35.07



Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

REFERENCE: Telecon C. Hooper (LP&L) and W. Crossman (NRC IV) on
February 15, 1984

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Potentially Reportable Deficiency No. 153
"Boston Insulated Wire and Cable Company (BIWC), QA Program
Deficiencies"
Final Report

On February 15, 1984, a problem with the subject Vendor's Quality Assurance Program was reported as PRD No. 153. Further evaluation of the previously described condition indicates this condition is not considered reportable pursuant to 10CFR50.55(e).

EVALUATION

Investigation into results of the audit conducted in January 1984 and a reaudit of BIWC in March 1984 identified the following:

- a. The January 1984 audit was terminated early due to a blizzard being imminent. No post audit conference was conducted for presentation of the auditors concerns due to a lack of availability of management personnel.
- b. A reaudit in March 1984 verified the Vendors' program to be satisfactory and B.I.W.C. was reinstated on the Qualified Suppliers List. Additionally, those concerns from the January 1984 audit were presented to BIWC management who were able to satisfactorily answer the concerns.

8404190102 840405
PDR ADOCK 05000382
S PDR


IE-27

1/0

Mr. John T. Collins
April 5, 1984
W3K84-0817
Page 2

If the January 1984 audit had contained a post audit conference with BIWC management, the concerns would have been resolved at that time as verified by the March 1984 reaudit. Therefore, this item is considered not reportable.

Very truly yours,



T. F. Gerrets
Quality Assurance Manager

TFG:CNH:VBR

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. E. L. Blake
Shaw, Pittman, Potts & Trowbridge
1800 M Street, N.W.
Washington, D.C. 20036

Mr. W. M. Stevenson
Monroe & Lemann
1424 Whitney Building
New Orleans, Louisiana 70130

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

Mr. W. A. Cross
7910 Woodmont Avenue
Suite 1200
Bethesda, Maryland 20814