

Duke Power Company
McGuire Nuclear Generation Department
12700 Hagers Ferry Road (MG01VP)
Huntersville, NC 28078-8985

T. C. McMEEKIN
Vice President
(704)875-4800
(704)875-4809 Fax



DUKE POWER

DATE: May 11, 1995

**U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555**

**Subject: McGuire Nuclear Station Unit 1 and 2
Docket No. 50-369**

**Licensee Event Report 369/94-10, Revision 1
Problem Investigation Process No.: 2-M94-1697 And 1-M95-0246**

Gentlemen:

Pursuant to 10 CFR 50.73 Sections (a) (1) and (d), attached is Licensee Event Report 369/94-10, Revision 1, concerning Failure To Perform Technical Specifications Required Surveillances Because Testing Was Not Specified. This report is being submitted in accordance with 10 CFR 50.73 (a) (2) (i). This event is considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

A handwritten signature in dark ink, appearing to read 'T.C. McMeekin'.

T.C. McMeekin

RJD/bcb

Attachment

cc: Mr. S.D. Ebner
Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta St., NW, Suite 2900
Atlanta, GA 30323

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, GA 30339

Mr. Victor Nerses
U.S. Nuclear Regulatory Commission
Office of Nuclear Reactor Regulation
Washington, D.C. 20555

Mr. George Maxwell
NRC Resident Inspector
McGuire Nuclear Station

9505230095 950511
PDR ADDCK 05000369
S PDR

TE221

bxc: B.L. Walsh (EC11C)
Zack Taylor (CNS)
G.A. Copp (EC050)
J.I. Glenn (MG02-ME)
P.R. Herran (MG01VP)
Cindy Davis (MG01CP)
J. E. Burchfield (ONS Reg Compliance)
G.H. Savage (EC06E)
G.B. Swindlehurst (EC11-0842)
M.S. Tuckman (EC07H)
R.F. Cole (EC05N)
John Frye (EC05N)
Tim Becker (PB02L)
P.M. Abraham (EC08I)
Ronnie White (MG01VP)
L.V. Wilkie (ON03SR)
D.P. Kimball (CN05SR)
NSRB Support Staff (EC05N)
Kay Crane (MG01RC)
Rich Casler (EC05N)