



# MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

F. O. BOX 1640, JACKSON, MISSISSIPPI 39205

January 27, 1983

JAMES P. McGAUGHY, JR.  
ASSISTANT VICE PRESIDENT

Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta St., N.W., Suite 3100  
Atlanta, Georgia 30303


Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station  
Unit 1  
Docket No. 50-416  
License No. NPF-13  
File 0260/L-835.0  
Heat Detectors in the Control  
Room Standby Fresh Air  
System Not Functionally  
Tested  
LER 83-002/01 T-0  
AECM-83/60

On January 14, 1983, it was discovered that the heat detectors in the control room standby fresh air system had not been functionally tested. These detectors are required by Technical Specification 3.3.7.9. This event is reported pursuant to Technical Specification 6.9.1.12.b. Attached is LER 83-002/01 T-0.

Yours truly,

  
FOR J.P. McGaughy, Jr.

JPM:sap  
Attachment

cc: Mr. N. L. Stampley (w/a)  
Mr. R. B. McGehee (w/o)  
Mr. T. B. Colner (w/o)  
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Document Control Desk (w/a)  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

OFFICIAL COPY

TE 22

Member Middle South Utilities System

8302030110 830127  
PDR ADOCK 05000416  
PDR  
S