

LICENSEE EVENT REPORT

Attachment to AECEM-83/66

Page 1 of 1

CONTROL BLOCK:

--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M S G C S I 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5
7 8 9 14 15 25 26 30 37 38

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T

REPORT SOURCE L 6 0 5 0 0 0 4 1 6 7 1 2 2 9 8 2 8 0 1 2 8 8 3 9

2 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2	Smoke detection Zone 2-17 (East Corridor; Auxiliary Building, elevation 103 feet)
---	---	---

03 | alarmed and would not reset. Investigation revealed no smoke or fumes in the area.

0 4 | A fire watch was established in accordance with T.S.3.3.7.9. The event had no effect

05 | on the health and safety of the public and did not constitute a threat to plant safety.

0	6
---	---

 This event is reported pursuant to T.S.6.9.1.13.b.

0	7	
---	---	--

08 _____ 8

7 8 9

0 9

7 8

SYSTEM CODE

A B 11

9 10

CAUSE CODE

X 12

11

CAUSE SUBCODE

Z 13

12

COMPONENT CODE

I N S T R U 14

13 18

COMP. SUBCODE

E 15

19

VALVE SUBCODE

Z 16

20

(17) LER/RO REPORT NUMBER 8 2 —

EVENT YEAR 1 8 5 /

SEQUENTIAL REPORT NO. 0 3

CODE L —

TYPE 0

NO.

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
X				Z	Z	0000	N	N	A	H260
23	18	19		20	21	22	23	24	25	26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	The cause of the alarm is attributed to spurious actuation. The corrective actions
---	---	--

1 1 taken were to reset Zone 2-17 on the fire control panel and to functionally check the

1 2 detectors. The zone was returned to functional operability on January 12, 1983.

1 3 | Total time of the LCO was 13 days, 5 hours. All corrective action is considered _____

1	4
---	---

 complete. This is submitted as a final report.

7 8 9
FACILITY STATUS (1) 5 (2) G (28)
% POWER (10) 0 (11) 0 (12) 0 (13) 29 (29)
OTHER STATUS (30) NA
METHOD OF DISCOVERY (45) A (31) (46)
DISCOVERY DESCRIPTION (32) Alarmed Condition

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z 33 Z 34

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	2	(38)	NA	

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	8	0	0
0	0	0	40
		NA	

1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5															

8 9 10
PUBLICATION
ISSUED DESCRIPTION (45)
2 0 N 44
8302030569 830126
PDR ADOCK 05000416
S PDR
NRC USE ONLY
68 69 80

NAME OF PREPARER: Original signed by John P. Bailey

PHONE _____