

Arizona Public Service Company

April 12, 1984
ANPP-29284-BSK/TRB

U. S. Nuclear Regulatory Commission
Region V
Creskide Oaks Office Park
1450 Maria Lane - Suite 210
Walnut Creek, CA 94596-5368

Attention: Mr. T. W. Bishop, Director
Division of Resident
Reactor Projects and Engineering Programs

Subject: Time Extension For Report - DER 83-75
A 50.55(e) Potentially Reportable Deficiency Relating to Bolts
Securing the Two D0126SA Panel Filler Assemblies, Supplied by
Foxboro, were Improperly Torqued.
File: 84-019-026; D.4.33.2

Reference: (A) Telephone conversation between R. Dodds and R. Tucker on
November 2, 1983
(B) ANPP-28361, dated December 5, 1984 (Interim Report)
(C) ANPP-28663, dated January 23, 1984 (Time Extension)
(D) ANPP-28918, dated February 22, 1984 (Time Extension)


Dear Sir:

The NRC was notified of a potentially reportable deficiency in
Reference (A), an Interim Report was transmitted by Reference (B), and
Time Extensions were requested by Reference (C) and (D). At that time,
it was estimated that a Final Report would be available by April 19, 1984.

Due to the extensive investigation and evaluation required, it is now
expected that this information will be finalized by May 25, 1984, at
which time a complete report will be submitted.

There is no new information or change to the Interim Report at this time.

Very truly yours,



E. E. Van Brunt, Jr.
APS Vice President, Nuclear
ANPP Project Director

EEVB/TRB:db

cc: See Page Two

8404200298 840412
PDR ADDCK 05000528
S PDR

1E-27 1/0

Mr. T. W. Bishop
DER 83-75
Page Two

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.
W. E. Ide
D. B. Fasnacht
A. C. Rogers
B. S. Kaplan
L. A. Souza
J. Vorees
J. R. Bynum
P. P. Klute
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
H. D. Foster
D. R. Hawkinson
L. E. Vorderbrueggen
G. A. Fiorelli
S. R. Frost
J. Self
D. Canady

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, GA 30339